

For Professional Use Only



Absolute Concrete Products



Directions

Mix with a concrete mixer: 1 5-gallon bucket Overlay Stampable (Part A), 3-4 gallons LA-500 (Part B), and 100 lbs. aggregate to achieve the desired slump. If applied in high temperatures, additional LA-500 (Part B) may be necessary.

MARNING

 $\mathbf{\Lambda}$

Wear NIOSH/OSHA approved dust mask for silica bearing sands. Handle with gloves. Use eye protection. Control dust in the environment with ventilation. If eye irritation offurs, flush with water. Do not rub eyes. See a doctor if any problem persists.

Visit us at absoluteconcreteproducts.com